

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	308112
License plate	2AUG886
Vehicle identification number	W1K2470841J314836
Dossier	2021 050 090
Make	Mercedes B 180 Bus.Sol.
Mileage	42971
First registration	20/07/2021
client availability date	16/03/2026
inspectionDate	24/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
98	Rocker Panel Left / Cover Not Painted / Replace	N
111	Wing Rear Left // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y




## Damage Pictures




Damage within Renta-norm-scratch




Rocker Panel Left / Cover Not Painted / Replace-scratch




Bumper Front // Painting-scratch



Wing Rear Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Trunk Lid Interior Coating / Complete Panel / Replace-scratch