

INSPECTION REPORT

End of contract

GENERAL INFO

File	319382
License plate	2CKR640
Vehicle identification number	VF3M4DGZUNS120068
Dossier	2022140121
Make	Peugeot 3008 PHEV 165kW GT Pac
Mileage	43238
First registration	26/08/2022
client availability date	03/08/2026
inspectionDate	11/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
100	Door Rear Left // Smart Repair Small	Y
101	Door Rear Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
217	Door Front Right / Trim / Replace	N
282	Bumper Rear / Trim Center / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Rear Bonnet // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch




Door Rear Left // Smart Repair Medium-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch




Door Rear Left // Smart Repair Small-dent



Bumper Rear // Painting-bad repair



Door Front Right / Trim / Replace-tear



Front Bonnet // Painting-stone chipping