

INSPECTION REPORT

End of contract

GENERAL INFO

File	319620
License plate	2ANZ544
Vehicle identification number	VF3YCBNFB12S90843
Dossier	2021048029
Make	Peugeot Box.HDI 335 L2H2 140 P
Mileage	55640
First registration	31/05/2021
client availability date	05/08/2026
inspectionDate	19/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
84	Door Front Left // Repair & Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	Y
118	Wing Rear Left / Fuel Cover / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
198	Door Rear Right / Door Handle / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
258	Towing Cover Rear // Replace	N
294	Rear Loading Door Left // Repair & Painting	Y
303	Rear Loading Door Right // Painting	N
412	Seat Front Left / Bottom Coating / Replace	N
562	Dashboard / Instruments Panel / Replace	N
569	Dashboard / Steering Wheel / Replace	N
614	Front Left Door Interior Coating // Replace Completely	N


Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch




Wing Rear Right // Painting-scratch



Rear Loading Door Left // Repair & Painting-scratch



Rear Loading Door Right // Painting-scratch





Rocker Panel Left // Smart Repair Medium-scratch



Towing Cover Rear // Replace-dent




Wing Rear Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Wing Rear Left / Fuel Cover / Replace-cracked



Seat Front Left / Bottom Coating / Replace-stain



Front Left Door Interior Coating // Replace Completely-stain



Dashboard / Steering Wheel / Replace-stain





Bumper Rear / Lower Cover Not Painted / Replace-stain



Door Rear Right / Door Handle / Replace-stain



Door Rear Right // Painting-Chipped paint



Dashboard / Instruments Panel / Replace-hole





Lettering Removal 15min-