

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309778
License plate	2AAL868
Vehicle identification number	W1K1771121J295121
Dossier	2020234019
Make	Mercedes A Berline 200 d Bus.S
Mileage	66351
First registration	01/02/2021
client availability date	03/04/2026
inspectionDate	15/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	N
13	Bumper Front // Painting	N
63	Wing Front Left // Painting	N
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
113	Wing Rear Left // Painting	N
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
431	Seat Rear Left // Repair	N
860	Interior Cleaning // Small	N

## Damage Pictures



Door Front Right // Repair & Painting-scratch + dent



Wing Front Left // Painting-bad repair



Door Rear Left // Painting-bad repair



Wing Rear Left // Painting-bad repair




Door Front Left // Painting-bad repair



Rear Bonnet // Polish-Chemical reaction



Interior Cleaning // Small-stain



Bumper Rear // Polish-scratch



Seat Rear Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch




Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent