

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	280809
License plate	1XPL255
Vehicle identification number	WAUZZZGB7LR040579
Dossier	2019357165
Make	Audi A1SB 25 TFSI 70kW
Mileage	77825.00
First registration	27/02/2020
	16/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
84	Door Front Left // Repair & Painting	Y
134	Bumper Rear // Repair & Painting	N
163	Roof // Repair & Painting	N
188	Wing Rear Right / Fuel Cover / Replace	N
194	Door Rear Right // Repair & Painting	N
225	Side View Mirror Right // Polish	Y
236	Wing Front right // Polish	Y
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
331	Wheel Alloy Rear Right // Repair	N


Damage Pictures



Wheel Alloy Rear Right // Repair-scratch



Side View Mirror Right // Polish-scratch




Wing Front right // Polish-scratch








Bumper Front / Trim Right / Replace-scratch



Bumper Front / Trim Left / Replace-scratch




Door Rear Right // Repair & Painting-dent




Roof // Repair & Painting-dent



Bumper Rear // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Wing Rear Right / Fuel Cover / Replace-N comf / out of order