

INSPECTION REPORT


End of contract

GENERAL INFO

File	310675
License plate	2BLZ482
Vehicle identification number	VR3EFYHT2MN549463
Dossier	2021 361 004
Make	Peugeot Part.1.5BHDi 102 L1 L
Mileage	116681
First registration	10/01/2022
client availability date	20/04/2026
inspectionDate	30/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	Y
93	Rocker Panel Left // Repair & Painting	N
137	Bumper Rear // Replace without painting	Y
174	Light / Rear Right / Replace	N
244	Light / Front Right / Replace	Y
257	Front / Towing Cover / Replace	N
294	Rear Loading Door Left // Repair & Painting	N
840	Interior Cleaning // Large	N

Damage Pictures



Damage within Renta-norm-



Bumper Rear // Replace without painting-scratch



Rocker Panel Left // Repair & Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Light / Front Right / Replace-scratch



Rear Loading Door Left // Repair & Painting-scratch + dent



Light / Rear Right / Replace-cracked



Front / Towing Cover / Replace-missing



Interior Cleaning // Large-stain