

INSPECTION REPORT


End of contract

GENERAL INFO

File	320585
License plate	2CXP241
Vehicle identification number	VR3FCYHZTNY645836
Dossier	2022 336 018
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	113618
First registration	05/01/2023
client availability date	20/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
77	Side View Mirror Left / Shell / Replace Not Painted	N
78	Side View Mirror Left / Direction Indicator / Replace	N
16	Bumper Front // Polish	Y
32	Front Bonnet // Painting	N
80	Door Front Left // Smart Repair Small	Y
100	Door Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
161	Roof // Smart Repair Medium	N
169	Rear Bonnet / Spoiler / Replace & Painting	Y
174	Light / Rear Right / Replace	Y
196	Door Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Interior // Repair 1-Incinerated



Rear Bonnet / Spoiler / Replace & Painting-Chemical reaction



Front Bonnet // Painting-Chemical reaction



Interior Cleaning // Small-stain



Front Left Door Interior Coating // Replace Completely-worn



Rear Right Door Interior Coating // Repair-hole



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Door Front Left // Smart Repair Small-dent



Door Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Door Front Right // Smart Repair Small-dent



Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Front // Polish-scratch



Bumper Rear // Painting-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Side View Mirror Left / Direction Indicator / Replace-cracked