

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	308405
License plate	2ADZ176
Vehicle identification number	VR3FBYHZTLY056256
Dossier	2020325046
Make	Peugeot 508 1.5 BHDi GT EAT8
Mileage	113389
First registration	04/03/2021
client availability date	23/03/2026
inspectionDate	31/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	Y
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
326	Tyre Rear Left // Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	Y
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	Y
412	Seat Front Left / Bottom Coating / Replace	Y
413	Seat Front Left / Rear Coating / Replace	Y
860	Interior Cleaning // Small	N


## Damage Pictures



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Painting-scratch




Door Front Left // Painting-scratch




Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Roof // Polish-scratch



Bumper Rear // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Rear Bonnet // Painting-bad repair



Tyre Front Right // Replace-tear




Tyre Rear Left // Replace-tear



Tyre Rear Right // Replace-tear



Interior Cleaning // Small-stain



Seat Front Left / Rear Coating / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn