

INSPECTION REPORT


End of contract

GENERAL INFO

File	307693
License plate	2AAT380
Vehicle identification number	TMBJB7NS7M8038267
Dossier	2020 321 010
Make	Skoda Kod.1.5TSI 110kW Sportli
Mileage	101654
First registration	02/02/2021
client availability date	11/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	Y
193	Door Rear Right // Painting	N
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures





Damage within Renta-norm-scratch




Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Door Rear Right // Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Interior // Repair 1-hole



Rear Bonnet // Polish-scratch



Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch