

INSPECTION REPORT



End of contract

GENERAL INFO

File	314847
License plate	1YXQ122
Vehicle identification number	VF3LCYHZJLS305686
Dossier	2020268131
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	134982
First registration	22/01/2021
client availability date	12/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
234	Wing Front right // Repair & Painting	N
244	Light / Front Right / Replace	N
80	Door Front Left // Smart Repair Small	Y
100	Door Rear Left // Smart Repair Small	Y
112	Wing Rear Left // Smart Repair Large	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
181	Wing Rear Right // Smart Repair Medium	Y
203	Rocker Panel Right // Repair & Painting	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	Y
540	Interior // Repair 1	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N
774	Interior / Side Cover rear Seat / Replace	N
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Tyre Front Right // Replace-tear




Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Interior // Repair 1-hole



Roof // Smart Repair Medium-dent



Door Rear Left // Smart Repair Small-dent



Wing Rear Left // Smart Repair Large-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Rear Left Door Interior Coating // Replace Completely-scratch



Interior / Side Cover rear Seat / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Rear Bonnet / Rear Window / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wing Rear Right // Smart Repair Medium-scratch



Wheel Alloy Rear Left // Repair-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Light / Front Right / Replace-scratch



Wing Front right // Repair & Painting-scratch + dent



Bumper Front // Replace & Painting-cracked