

INSPECTION REPORT





End of contract


GENERAL INFO

File	321381
License plate	2BJM594
Vehicle identification number	W1N2477861J338277
Dossier	2021011039
Make	Mercedes GLA 250e Business Sol
Mileage	55320
First registration	08/12/2021
client availability date	02/09/2026
inspectionDate	17/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
32	Front Bonnet // Painting	N
237	Wing Front right / Trim / Replace	N
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	N
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	Y

Damage Pictures



Light / Rear Right / Replace-scratch





Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Right // Repair & Painting-scratch + dent





Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Windshield // Repair-cracked



Light / Rear left / Replace-cracked



Tyre Front Right // Replace-tear



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Painting-scratch



Front Bonnet // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front right / Trim / Replace-scratch