

INSPECTION REPORT



End of contract


GENERAL INFO

File	316219
License plate	2CEB235
Vehicle identification number	VR3FCYHZTNY558967
Dossier	2021 062 144
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	240091
First registration	20/06/2022
client availability date	25/06/2026
inspectionDate	21/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
124	Light / Rear left / Replace	N
125	Light / Rear Left On Rear Bonnet / Replace	N
891	Lettering Removal 15min	N
16	Bumper Front // Polish	Y
80	Door Front Left // Smart Repair Small	Y
88	Door Front Left / Door Handle / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
114	Wing Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
151	Rear Bonnet // Smart Repair Medium	Y
161	Roof // Smart Repair Medium	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
431	Seat Rear Left // Repair	Y
540	Interior // Repair 1	Y
541	Interior // Repair 2	N
551	Central Console // Repair	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
644	Rear Right Door Interior Coating // Replace Completely	Y

774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures




Bumper Rear / Lower Cover Not Painted / Replace-scratch




Bumper Rear // Painting-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Rear Bonnet // Smart Repair Medium-scratch



Wheel Alloy Rear Right // Repair-scratch




Door Rear Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Front // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch




Rear Left Door Interior Coating // Repair-scratch



Interior // Repair 1-scratch



Seat Rear Left // Repair-scratch



Door Rear Left // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent




Door Front Right // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Roof // Smart Repair Medium-scratch + dent



Door Front Left / Door Handle / Replace-missing



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Central Console // Repair-Chipped paint



Interior // Repair 2-bad position



Rear Right Door Interior Coating // Repair-hole



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Lettering Removal 15min-