

INSPECTION REPORT



End of contract

GENERAL INFO

File	309431
License plate	2AFU529
Vehicle identification number	VF3LCYHZJMS045022
Dossier	2020 286 057
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	87953
First registration	22/03/2021
client availability date	30/03/2026
inspectionDate	03/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	N
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
166	Roof / Antenna / Replace	N
202	Rocker Panel Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	N
565	Dashboard / Storage Tray / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Side View Mirror Left // Painting-scratch



Dashboard / Storage Tray / Replace-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Alloy Front Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Rocker Panel Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Painting-scratch



Door Front Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Trunk Compartment / Side Cover Right / Replace-missing



Roof / Antenna / Replace-missing