

INSPECTION REPORT

End of contract

GENERAL INFO

File	307355
License plate	2FHX813
Vehicle identification number	SJNFAAF16U1289143
Dossier	2023361013
Make	Nissan Juke 1.0 84kW N-Design
Mileage	12660
First registration	16/05/2024
client availability date	04/03/2026
inspectionDate	16/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
18	Bumper Front / Spoiler / Replace	N
103	Door Rear Left // Painting	N
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
165	Roof // Polish	Y
196	Door Rear Right // Polish	Y
225	Side View Mirror Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures







Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right // Polish-scratch



Door Rear Right // Polish-scratch




Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Painting-scratch + dent



Bumper Front / Spoiler / Replace-cracked



Wing Rear Left // Polish-Chemical reaction



Roof // Polish-Chemical reaction



Interior Cleaning // Small-dirty