

INSPECTION REPORT

End of contract

GENERAL INFO

File	319811
License plate	2BTC119
Vehicle identification number	VR3UDYH5KNJ541747
Dossier	2021306108
Make	Peugeot 2008 1.5BlueHDi 81kW A
Mileage	135125
First registration	14/03/2022
client availability date	07/08/2026
inspectionDate	18/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	N
214	Door Front Right // Repair & Painting	N
234	Wing Front right // Repair & Painting	N
237	Wing Front right / Trim / Replace	N
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
891	Lettering Removal 15min	N
38	Front Bonnet / Insulation / Replace	N
80	Door Front Left // Smart Repair Small	Y
134	Bumper Rear // Repair & Painting	N
157	Rear Bonnet / Trim / Replace	Y
161	Roof // Smart Repair Medium	Y
175	Light / Rear Right On Rear Bonnet / Replace	N
190	Door Rear Right // Smart Repair Small	Y
205	Rocker Panel Right // Polish	Y
219	Door Front Right / Window / Replace	Y
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Light / Rear Right On Rear Bonnet / Replace-scratch




Rear Bonnet / Trim / Replace-scratch



Rocker Panel Right // Polish-scratch



Door Front Right / Window / Replace-scratch



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Door Front Left // Smart Repair Small-scratch




Wheel Alloy Rear Left // Repair-scratch




Interior / Side Cover rear Seat / Replace-scratch



Door Rear Right // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Bumper Rear // Repair & Painting-dent



Wheel Alloy Front Right // Repair-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Polish-scratch



Door Front Right // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Lettering Removal 15min-



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch