

INSPECTION REPORT

End of contract

GENERAL INFO

File	307459
License plate	2ACR777
Vehicle identification number	W1K1770861J300257
Dossier	2020 259 064
Make	Mercedes A 250e PHEV Bus.Sol.A
Mileage	53139
First registration	22/02/2021
client availability date	13/03/2026
inspectionDate	01/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	N
114	Wing Rear Left // Repair & Painting	N
274	Bumper Front / Grid Central / Replace	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y

Damage Pictures



Damage within Renta-norm-





Door Rear Left // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Wheel Two Tone Rear Left // Repair-Chemical reaction



Bumper Front / Grid Central / Replace-bad position