

INSPECTION REPORT

End of contract

GENERAL INFO

File	307596
License plate	2BFT169
Vehicle identification number	W0VBE6EV2NG029599
Dossier	2021242046
Make	Opel Astra 1.5D 90kW Ultimate
Mileage	98385
First registration	05/11/2021
client availability date	12/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	N
113	Wing Rear Left // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
326	Tyre Rear Left // Replace	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Damage within Renta-norm-



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch




Wheel Alloy Front Right // Repair-scratch



Tyre Rear Left // Replace-tear



Interior Cleaning // Small-stain



Wheel Alloy Front Left // Repair-scratch



Door Rear Left // Painting-scratch



Wing Rear Left // Painting-scratch