

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309430
License plate	2AFU520
Vehicle identification number	VF3LCYHZJMS045021
Dossier	2020 286 055
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	67097
First registration	22/03/2021
client availability date	30/03/2026
inspectionDate	02/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
258	Towing Cover Rear // Replace	N
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
80	Door Front Left // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	Y
203	Rocker Panel Right // Repair & Painting	N
236	Wing Front right // Polish	Y
271	Bumper Front / Trim Left / Replace	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
536	Trunk Compartment / Cover Storage Tray / Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
554	Central Console // Replace Completely	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
618	Front Left Door Interior Coating / Door Handle / Replace	Y
773	Interior / A Pillar Lower Cover / Replace	Y


## Damage Pictures



Bumper Front / Trim Left / Replace-bad position



Front Left Door Interior Coating / Door Handle / Replace-scratch



Central Console // Replace Completely-scratch




Wing Rear Right // Repair & Painting-scratch + dent




Rocker Panel Right // Repair & Painting-scratch + dent



Front Bonnet // Painting-bad repair



Trunk Compartment / Boot Cover / Replace-cracked



Interior // Repair 1-missing




Trunk Compartment / Cover Storage Tray / Replace-missing



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Rear Left // Repair-scratch



Bumper Front // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Dashboard / Steering Wheel / Replace-scratch



Roof // Smart Repair Medium-dent



Bumper Rear / Spoiler / Replace-scratch





Bumper Rear // Repair & Painting-scratch + dent



Towing Cover Rear // Replace-bad position