

INSPECTION REPORT


End of contract

GENERAL INFO

File	307657
License plate	2BWN723
Vehicle identification number	W1N1671541A658390
Dossier	2022 098 077
Make	Mercedes GLE 350 e 4M
Mileage	194827
First registration	20/04/2022
client availability date	10/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
221	Side View Mirror Right // Plastic Repair	N
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
117	Wing Rear Left / Trim / Replace	N
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
135	Bumper Rear // Replace & Painting	N
150	Rear Bonnet // Smart Repair Small	Y
196	Door Rear Right // Polish	Y
236	Wing Front right // Polish	Y
257	Front / Towing Cover / Replace	Y
258	Towing Cover Rear // Replace	Y
272	Bumper Front / Trim Right / Replace	N
320	Wheel Two Tone Rear Left // Repair	N
326	Tyre Rear Left // Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	Y
850	Certificate of Conformity //	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Interior Cleaning // Small-dirty



Wing Rear Left / Trim / Replace-tear



Tyre Rear Left // Replace-tear



Bumper Rear // Replace & Painting-tear



Tyre Front Right // Replace-tear



Front / Towing Cover / Replace-bad position



Towing Cover Rear // Replace-bad position




Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Door Rear Left // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch




Rear Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Front Bonnet // Painting-bad repair



Bumper Front / Trim Right / Replace-cracked



Wing Front right // Polish-scratch



Light / Rear left / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-cracked