

INSPECTION REPORT




End of contract

GENERAL INFO

File	320753
License plate	2BVY563
Vehicle identification number	VSSZZZKLZNR044866
Dossier	2022088023
Make	Seat Leon ST 2.0TDI 115 Move!
Mileage	151782
First registration	12/04/2022
client availability date	01/09/2026
inspectionDate	14/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
13	Bumper Front // Painting	Y
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
233	Wing Front right // Painting	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wing Rear Left // Repair & Painting-scratch + dent




Interior Cleaning // Small-stain



Windshield // Replace-stone chipping



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Wheel Alloy Rear Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Side View Mirror Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Painting-scratch




Wheel Alloy Front Right // Repair-scratch



Wing Front right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Smart Repair Small-dent



Bumper Rear / Spoiler / Replace-scratch + dent





Bumper Rear // Repair & Painting-scratch + dent