

INSPECTION REPORT


End of contract

GENERAL INFO

File	314558
License plate	2AQE265
Vehicle identification number	W1K1186101N232902
Dossier	2020364069
Make	Mercedes CLA SB 180 d Bus.Sol.
Mileage	28500
First registration	09/06/2021
client availability date	04/06/2026
inspectionDate	18/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
78	Side View Mirror Left / Direction Indicator / Replace	N
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
154	Rear Bonnet // Repair & Painting	Y
543	Interior // Ionization Odor	N


Damage Pictures



Door Front Left // Smart Repair Medium-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent