

INSPECTION REPORT

End of contract

GENERAL INFO

File	316269
License plate	2CGF674
Vehicle identification number	VSSZZZKJZNR098119
Dossier	2022 179 021
Make	Seat Arona 1.0 81kW Move DSG
Mileage	54956
First registration	13/07/2022
client availability date	25/06/2026
inspectionDate	27/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
13	Bumper Front // Painting	Y
271	Bumper Front / Trim Left / Replace	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
187	Wing Rear Right / Trim / Replace	Y
549	Interior / Headliner/ Replace	Y
840	Interior Cleaning // Large	Y

Damage Pictures



Interior / Headliner/ Replace-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Interior Cleaning // Large-stain



Wing Rear Right / Trim / Replace-bad position



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Painting-scratch