

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	311308
License plate	2BPT157
Vehicle identification number	SB1Z93BE60E271692
Dossier	2021293126
Make	Toyota Corolla TS 1.8 Hybrid D
Mileage	91118
First registration	08/02/2022
client availability date	28/04/2026
inspectionDate	30/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
133	Bumper Rear // Painting	N
161	Roof // Smart Repair Medium	Y
184	Wing Rear Right // Repair & Painting	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
561	Dashboard // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures




Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Painting-scratch



Roof // Smart Repair Medium-dent





Dashboard // Repair-dent



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Interior Cleaning // Small-stain