

INSPECTION REPORT




End of contract

GENERAL INFO

File	321107
License plate	2BBB482
Vehicle identification number	TMBJJ7NS7M8034836
Dossier	2021251073
Make	Skoda Kod.2.0CRTDI 110kW Sport
Mileage	181397
First registration	15/09/2021
client availability date	28/08/2026
inspectionDate	09/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
81	Door Front Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
213	Door Front Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch