

INSPECTION REPORT

End of contract


GENERAL INFO

File	316605
License plate	CC1150
Vehicle identification number	YV1ZWK5VDN2467134
Dossier	2021047044
Make	Volvo V60 B4 2.0 197 Momen.Cor
Mileage	163245
First registration	07/07/2021
client availability date	30/06/2026
inspectionDate	02/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
213	Door Front Right // Painting	N
234	Wing Front right // Repair & Painting	N
15	Bumper Front // Replace & Painting	N
32	Front Bonnet // Painting	N
41	Windshield // Replace	Y
83	Door Front Left // Painting	Y
113	Wing Rear Left // Painting	N
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	Y
412	Seat Front Left / Bottom Coating / Replace	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
560	Interior / A Pillar Cover / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Front // Replace & Painting-cracked



Seat Front Left / Bottom Coating / Replace-Incinerated



Interior // Repair 1-Incinerated



Interior / A Pillar Cover / Replace-Incinerated



Windshield // Replace-glass damage



Interior Cleaning // Small-stain



Door Rear Right // Polish-scratch



Wing Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Front Bonnet // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Door Front Right // Painting-scratch



Wing Front right // Repair & Painting-scratch + dent