

INSPECTION REPORT

End of contract

GENERAL INFO

File	314416
License plate	1YMR632
Vehicle identification number	VF3VFAHKKLZ063563
Dossier	2020084044
Make	Peugeot Expert 2.0BHDi 120 L3
Mileage	86944
First registration	21/10/2020
client availability date	03/06/2026
inspectionDate	10/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
271	Bumper Front / Trim Left / Replace	N
273	Bumper Front / Grid Left / Replace	N
274	Bumper Front / Grid Central / Replace	N
275	Bumper Front / Grid Right / Replace	N
35	Front Bonnet // Polish	Y
65	Wing Front Left // Replace & Painting	N
84	Door Front Left // Repair & Painting	N
86	Door Front Left // Polish	Y
87	Door Front Left / Trim / Replace	N
93	Rocker Panel Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	N
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
162	Roof // Painting	N
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	N
197	Door Rear Right / Trim / Replace	N
201	Rocker Panel Right // Smart Repair Medium	N
217	Door Front Right / Trim / Replace	N
222	Side View Mirror Right // Painting	N
235	Wing Front right // Replace & Painting	N
294	Rear Loading Door Left // Repair & Painting	N
304	Rear Loading Door Right // Repair & Painting	N
412	Seat Front Left / Bottom Coating / Replace	Y
418	Seat Front Left / Armrest / Replace	N
540	Interior // Repair 1	N
569	Dashboard / Steering Wheel / Replace	Y
598	Trunk Lid Interior Coating / Handle / Replace	Y

631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
840	Interior Cleaning // Large	N

Damage Pictures



Wing Front Left // Replace & Painting-rust



Rocker Panel Right // Smart Repair Medium-rust



Wing Rear Left // Repair & Painting-rust



Wing Rear Right // Repair & Painting-rust



Wing Front right // Replace & Painting-rust



Door Front Left // Polish-Chemical reaction



Roof // Polish-Chemical reaction



Roof // Painting-Chemical reaction



Interior Cleaning // Large-stain



Dashboard / Steering Wheel / Replace-worn




Front Bonnet // Polish-Remainder stickers



Seat Front Left / Bottom Coating / Replace-hole




Seat Front Left / Armrest / Replace-hole




Rocker Panel Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent




Door Front Left / Trim / Replace-cracked



Door Front Right / Trim / Replace-scratch




Side View Mirror Right // Painting-scratch



Interior // Repair 1-scratch



Rear Right Door Interior Coating // Repair-scratch



Rear Left Door Interior Coating // Repair-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Painting-scratch



Trunk Lid Interior Coating / Handle / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front / Grid Left / Replace-scratch



Bumper Front / Grid Right / Replace-scratch



Bumper Front / Grid Central / Replace-cracked



Bumper Front // Replace & Painting-cracked