

# INSPECTION REPORT


End of contract


## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 314399                         |
| License plate                 | XY4769                         |
| Vehicle identification number | VR3USHNSSNJ662371              |
| Dossier                       | 2021342044                     |
| Make                          | Peugeot 2008 1.2 PT 130 Allure |
| Mileage                       | 29615                          |
| First registration            | 26/07/2022                     |
| client availability date      | 03/06/2026                     |
| inspectionDate                | 06/06/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | N       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | N       |        |
| Registration certificate  |        | N       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                             | Acceptable |
|---------|--------------------------------------------------|------------|
| 132     | Bumper Rear // Smart Repair Large                | N          |
| 151     | Rear Bonnet // Smart Repair Medium               | N          |
| 13      | Bumper Front // Painting                         | N          |
| 19      | Bumper Front / Lower Cover Not Painted / Replace | N          |
| 67      | Wing Front Left / Trim / Replace                 | N          |
| 237     | Wing Front right / Trim / Replace                | N          |
| 273     | Bumper Front / Grid Left / Replace               | N          |
| 275     | Bumper Front / Grid Right / Replace              | N          |
| 41      | Windshield // Replace                            | N          |
| 80      | Door Front Left // Smart Repair Small            | Y          |
| 138     | Bumper Rear / Lower Cover Not Painted / Replace  | Y          |
| 147     | Back Side / Whiper Arm / Replace                 | N          |
| 183     | Wing Rear Right // Painting                      | Y          |
| 193     | Door Rear Right // Painting                      | Y          |
| 210     | Door Front Right // Smart Repair Small           | Y          |
| 225     | Side View Mirror Right // Polish                 | Y          |
| 320     | Wheel Two Tone Rear Left // Repair               | N          |
| 540     | Interior // Repair 1                             | N          |

## Damage Pictures



Side View Mirror Right // Polish-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch




Door Front Left // Smart Repair Small-scratch







Door Front Right // Smart Repair Small-dent



Back Side / Whiper Arm / Replace-cracked



Interior // Repair 1-cracked



Windshield // Replace-glass damage



Bumper Rear // Smart Repair Large-scratch



Rear Bonnet // Smart Repair Medium-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Grid Left / Replace-scratch



Bumper Front / Grid Right / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch