

INSPECTION REPORT


End of contract

GENERAL INFO

File	320960
License plate	CU5089
Vehicle identification number	LYVUZK9VDNB092859
Dossier	2022116010
Make	Volvo XC60 B4P 197 MHEV AWD In
Mileage	59091
First registration	26/08/2022
client availability date	27/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
156	Rear Bonnet // Polish	Y
193	Door Rear Right // Painting	N
216	Door Front Right // Polish	Y
219	Door Front Right / Window / Replace	Y
230	Wing Front right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Polish-scratch




Door Front Left // Smart Repair Small-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Wing Front right // Smart Repair Small-dent



Door Rear Right // Painting-bad repair



Front Bonnet // Polish-Chemical reaction




Door Front Right / Window / Replace-scratch



Door Front Right // Polish-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch