

INSPECTION REPORT


End of contract

GENERAL INFO

File	320819
License plate	1YRE264
Vehicle identification number	VR3FBYHZJLY043098
Dossier	2020141063
Make	Peugeot 508 1.5 BHDi Active
Mileage	71271
First registration	02/01/2021
client availability date	24/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
41	Windshield // Replace	Y
64	Wing Front Left // Repair & Painting	Y
104	Door Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
194	Door Rear Right // Repair & Painting	N
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	Y
233	Wing Front right // Painting	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
883	Key Price Range 2 //	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wing Front right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Windshield // Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Painting-scratch



Bumper Front // Repair & Painting-dent



Wing Front Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent