

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	314119
License plate	2ALP283
Vehicle identification number	VR3FCYHZTMY011768
Dossier	2021018104
Make	Peugeot 508SW 1.5 BHDi GT EAT8
Mileage	153516
First registration	05/05/2021
client availability date	01/06/2026
inspectionDate	06/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
184	Wing Rear Right // Repair & Painting	N
13	Bumper Front // Painting	N
63	Wing Front Left // Painting	N
81	Door Front Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	N
116	Wing Rear Left // Polish	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures



Interior // Repair 1-Incinerated



Interior Cleaning // Small-stain



Seat Front Left / Bottom Coating / Replace-worn





Wing Rear Left // Polish-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch





Wing Front Left // Painting-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Bumper Rear // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent