

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	313606
License plate	JV5913
Vehicle identification number	VR3USHNSSNJ662326
Dossier	2021342070
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	49810
First registration	26/07/2022
client availability date	22/05/2026
inspectionDate	27/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






## DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
193	Door Rear Right // Painting	N
197	Door Rear Right / Trim / Replace	N
13	Bumper Front // Painting	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
181	Wing Rear Right // Smart Repair Medium	N
225	Side View Mirror Right // Polish	Y
774	Interior / Side Cover rear Seat / Replace	N

## Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Front Left // Painting-scratch



Door Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Medium-scratch + dent




Bumper Front // Painting-bad repair



Front Bonnet / Insulation / Replace-cracked




Side View Mirror Right // Polish-scratch



Windshield // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Painting-scratch



Wing Rear Right / Trim / Replace-scratch