

INSPECTION REPORT


End of contract


GENERAL INFO

File	307705
License plate	2ABN430
Vehicle identification number	TMBAG7NX5MY112654
Dossier	2020279113
Make	Skoda Octavia 2.0TDI 85kW Ambi
Mileage	72181
First registration	10/02/2021
client availability date	16/03/2026
inspectionDate	19/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
33	Front Bonnet // Repair & Painting	N
41	Windshield // Replace	Y
111	Wing Rear Left // Smart Repair Medium	N
162	Roof // Painting	N
412	Seat Front Left / Bottom Coating / Replace	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures





Damage within Renta-norm-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch





Wing Rear Left // Smart Repair Medium-scratch



Roof // Painting-scratch




Bumper Front // Painting-scratch





Front Bonnet // Repair & Painting-scratch + dent



Windshield // Replace-glass damage



Interior Cleaning // Small-stain



Seat Front Left / Bottom Coating / Replace-hole