

INSPECTION REPORT


End of contract


GENERAL INFO

File	320181
License plate	NA5205
Vehicle identification number	ZARNASAS6N3055031
Dossier	2023065015
Make	Alfa Romeo Tonale 1.6Ddct129 S
Mileage	12015
First registration	21/12/2023
client availability date	13/08/2026
inspectionDate	18/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
190	Door Rear Right // Smart Repair Small	Y
214	Door Front Right // Repair & Painting	N
538	Trunk Compartment / Boot Cover / Replace	N

Damage Pictures



Door Rear Right // Smart Repair Small-scratch



Door Front Left // Smart Repair Small-scratch



Door Front Right // Repair & Painting-dent



Trunk Compartment / Boot Cover / Replace-missing