

INSPECTION REPORT


End of contract

GENERAL INFO

File	307690
License plate	2CGQ552
Vehicle identification number	TMBJG7NX2NY119031
Dossier	2021 272 120
Make	Skoda Oct.Com.2.0TDI 85kW Clev
Mileage	185526
First registration	18/07/2022
client availability date	10/03/2026
inspectionDate	19/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
41	Windshield // Replace	N
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
162	Roof // Painting	Y
540	Interior // Repair 1	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N
883	Key Price Range 2 //	N

Damage Pictures



Damage within Renta-norm-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Trunk Lid Interior Coating / MDF Rear Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Painting-scratch



Wing Rear Left // Polish-scratch



Bumper Front // Smart Repair Medium-scratch



Windshield // Replace-glass damage



Key Price Range 2 //-missing





Interior Cleaning // Small-stain



Interior // Repair 1-hole



Roof // Painting-scratch